Amplifier installation diagram



There are no cathode resistors on cathodes V3 and V4.
Cathodes V3 and V4 are connected directly to AB-Q-MKIII.

Resistor R39 in the bias source must be replaced with a value of

15 Ohm

Schematic diagram